

# CLPe Firmware Release R02.10.03

## Release Notes January 11th 2021

<p>Fixes / Enhancements:</p>	<p>Firmware release R02.10.03 provides a patch to upgrade and resolve following items:-</p> <ul style="list-style-type: none"> <li>- Fix LED misbehaviour during interaction of Mute/Unmute with Dynamic Talkaround Scan</li> <li>- Fix LED misbehaviour during interaction of Voice call with Mute/Unmute in Repeater and TA mode</li> <li>- Fix Vox mode not working properly after enable via Vox powerup sequence</li> <li>- Improve Scramble 3 mode audio performance</li> <li>- Increase mic gain to improve audio performance when mic far from mouth (eg. clipped to chest)</li> </ul>
<p>Applicable EMEA Models:</p>	<p>PMUE5510A - CLP446e 0.5W PMR446 EMEA          PMUE5512A - CLP446e 0.5W PMR446 MULTIPACK EMEA          PMUE5514A - CLPe PLUS UHF EMEA          PMUE5516A - CLPe PLUS UHF MULTIPACK EMEA</p>
<p>Previous versions compatible with this update:</p>	<p>FW R02.10.00 CP R02.00.00          FW R02.10.00 CP R02.00.01          FW R02.10.01 CP R02.00.01          FW R02.10.02 CP R02.00.01</p>